

Ultradot Limited Lifetime Warranty

Ultradot Distribution Inc., warrants Ultradot electronic sights to be free from defects in materials and workmanship. (Please see: Covered Defects) Ultradot Distribution, Inc., will repair or replace, as it deems most suitable, any product which is defective in material or workmanship without charge (above shipping and handling) during the warranty term of the original purchaser, provided the product is returned by the original purchaser. All costs associated with the shipment of the product are the responsibility of the original purchaser. This warranty does not cover defects caused by improper handling, incorrect installation, regular maintenance not performed (Please see: Regular Required Maintenance), abnormal use, alteration, accident or normal wear and tear. (please see: Not Covered Defects)

Ultradot Distribution Inc., shall not be liable for consequential damages. Including but not limited to commercial or other economic loss or lost profits, or incidental damages. Some states do not allow the exclusion or limitation of incidental or consequential damages, so the above limitation or exclusion may not apply to you. All implied warranties, if any arise under state law are limited in duration to the duration of this written warranty. Except for such implied warranties, there are not other warranties which extend beyond this written warranty. Some states do not allow limitations on how long an implied warranty lasts, so the above limitation may not apply to you. This warranty gives you specific legal rights, and you may also have other rights which vary from state to state.

Covered Defects	Resolution	Comments
Debris on inside of tube or lens.	Sight to be repaired by service technician, cleaned and re-gassed.	
Moisture within tube.	Sight to be repaired by service technician, cleaned and re-gassed.	Caused by failed O-Ring seals.
Sight will not turn on.	Electronics to be repaired by service technician.	See Troubleshooting First.
Dot flickering or only working intermittently.	Electronics to be repaired by service technician.	See Troubleshooting First.
Sight tube not firmly attached to center hub.	Sight to be repaired by service technician, cleaned and re-gassed.	Often caused by solvents during gun cleaning.
Flawed lens.	Lens to be replaced by service technician, cleaned and re-gassed.	See Troubleshooting First.
Dot fails / flickers when brightness control knob is turned.	Electronics to be repaired by service technician.	See Troubleshooting First.
Reticle selector knob becomes loose on housing.	Sight to be repaired by service technician, cleaned and re-gassed.	
Brightness control knob becomes loose on housing.	Sight to be repaired by service technician, cleaned and re-gassed.	

Not Covered	Resolution	Comments
Broken lens.	Tube sights are repairable. Pan AV and L/T are not.	Improper handling or over tightened mounting rings.
Worn out brightness control knob.	Repairable.	Detents will wear over time or with excessive use.
Worn out reticle selector knob.	Repairable.	Detents will wear over time or with excessive use.
Polarizing filter.	Must be replaced by user.	This is an accessory.
Stripped mounting rings.	Must be replaced by user.	Caused by over tightening or improper alignment.
Stripped battery cover.	Must be replaced by user.	Caused by improper handling.
Battery.	Must be replaced by user.	Wears out with time and use.